MEN'S HEADWEAR

HOW TO MEASURE

HEAD: To figure out your UA fitted hat size, measure the circumference of your head where your hat will rest. If you don't have a tape measure, use a string and measure it against a ruler. Find your measurement on the size chart to determine your ideal UA hat size.

SIZE CHART

ADJUSTABLE CAP SIZE

	Head (cm)
MEN'S OSFA	56 - 60

STRETCH-FIT

	Head (cm)
S/M	53 - 55
M/L	56 - 58
L/XL	59 - 62
XL/XXL	63 - 65

Head (cm)

FITTED

US sizes

6 ^{5/8}	53
6 ^{3/4}	53.9
6 ^{7/8}	54.9
7	55.9
7 ^{1/8}	56.8
7 ^{1/4}	57.8
7 ^{3/8}	58.8
7 ^{1/2}	59.7
7 ^{5/8}	60.6
7 ^{3/4}	61.6
7 ^{7/8}	62.8
8	63.8

MEN'S GLOVES

81/8

HOW TO MEASURE

HANDS: On your dominant hand, measure from the base of your palm to the tip of your middle finger then use the chart to find your ideal UA glove size. You can also measure the circumference of your palm right under your fingers.

Palm to Finger

64.8

SIZE CHART

Men's

XS	17 - 18
S	18 - 18 ^{1/2}
М	18 ^{1/2} - 19
L	19 - 19 ^{1/2}
XL	19 ^{1/2} - 20
XXL	20 - 21
	Palm to Finger
S-C	Palm to Finger 17.5 - 18
S-C M-C	
	17.5 - 18
M-C	17.5 - 18 18 - 18.5



